

*RESPONSIBILITIES OF SUPPLIER AND BUYER*

---

	Supplier	Buyer
Define Performance Acceptance Test date and time	X	X
Agree on SAT methods and procedure	X	X
Designate representative to assist to the SAT	X	X
Agree on the product and packaging to run during the SAT	X	X
Is timely present at the test start	X	X
Signs the SAT result protocol	X	X
Provides, at his costs, consistent quality and supply (quantity, flow, etc..) of all product and materials needed on the line during the SAT		X
Agrees on the quality of the products and materials quality provided.	X	
Provides at least 6 hours of production without stoppages (materials or product shortages, change-over, priming, ramp-up, emptying, missing operators, etc..) during the test period.		X
Informs the operating and maintenance personal on the line about the SAT procedure, time and period, and about the restrictions in operation that it imposes.		X
Supply well trained and experienced operators to operate the line during the SAT.		X
Nominates a SAT responsible, who has power for decision and agreement		X
Does not operate the line unless it is proven that one or more operators supplied by the Buyer were not properly trained or enough experienced for line operation	X	
Is present during the SAT and participates to the data collection	X	
Provides the tools, software and measurement means necessary for achieving data acquisition	X	
Issues the Performance Test Result Report	X	